Oil Field Environmental Incident Summary

Responsible Party: SECURE ENERGY SERVICES USA, LLC **Well Operator:** SECURE ENERGY SERVICES USA, LLC

Well Name: WATFORD SWD 1

Field Name: PEMBROKE Well File #: 90166

Date Incident:9/5/2014Time Incident:08:21Facility ID Number:County:MCKENZIETwp:149Rng:98Sec:6Qtr

Location Description: Outside of tank farm

Submitted By: Sean Hammersmark Received By:

Contact Person: Sean Hammersmark

555 17TH ST STE 800 DENVER, CO 80202-3908

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: 1 Mile

Type of Incident Other

Release Contained in Dike Yes - On Facility Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Minor spill that was contained on site.

Areal Extent:

Contained

Potential Environmental Impacts:

Spill was contained Right away. Vac truck was called to suck up free liquids. Dirt was scraped up and disposed of.

Action Taken or Planned:

None needed.

Wastes Disposal Location: Free fluids were dealt with In house (Pumped back in to tanks) Ssoil

was craped up and disposed of at a licensed disposal facility.

Agencies Involved:

Updates

Date: 9/5/2014 Status: Reviewed; O&G Lead Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to other causes, remained on location within the diking according to the report. NDIC retains oversight.